

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20191614  
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                              | Inspector: | Outcome: | Date:                      |
|------------------------------------------|------------|----------|----------------------------|
| <b>All Rough Inspection - Commercial</b> | Robb Popp  | Partial  | Friday, September 03, 2021 |

Informational:  
1           THIRD FLOOR           —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*  
COMPLETE

\*\*\*BUILDING B\*\*\*  
COMPLETE

\*\*\*BUILDING A\*\*\*\*  
-COMPLETE

Informational:  
2           SECOND FLOOR           —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*  
COMPLETE

\*\*\*BUILDING B\*\*\*  
COMPLETE

\*\*\*BUILDING A\*\*\*  
CORRIDOR CEILINGS TO SHAFT WALL

ROOMS: 2001,2002, 2017,2018,2043, 2045,2046, 2047  
STAIRWELL WALLS AND CEILING

Informational:

3 FIRST FLOOR

—AREAS APPROVED—

\*\*\*BUILDING C\*\*\*

CORRIDOR CEILINGS TO SHAFT WALL  
ROOMS:1015,1017,1020-1030  
STAIRWELL WALLS AND CEILING

\*\*\*BUILDING B\*\*\*

CORRIDOR CEILINGS TO SHAFT WALL  
ROOMS: 1002-1015  
STAIRWELL WALLS AND CEILING

\*\*\*BUILDING A\*\*\*

CORRIDOR CEILING TO SHAFT WALL  
EXTERIOR WALL 1032 OK TO INSULATE  
STAIRWELL WALLS AND CEILING  
ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059,  
1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058  
ROOM 1041 OK FOR SOFFIT FRAMING  
STAIRWELL WALLS AND CEILING

\*\*MCAL BUILDING\*\*

--- PRE ROCK:  
MECHANICAL ROOM 165 NORTH WALL  
ROOM 156  
Kitchen 164 OK  
CORRIDOR 167 TO 10' FROM SHAFT WALL  
CORRIDOR 169 TO RM 123  
CORRIDOR 172 TO RM 110  
CORRIDOR 173 TO RM 102  
SHARED SPACES OK FOR RC 150-174

UNITS: 102-147

Corrective Action Required:

4 Miscellaneous  
Correction

2044-INCOMPLETE  
2045-INCOMPLETE  
024-REPAIR TRUSS  
MCAL-

Comments: