

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210596
Address: 2102 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|------------------------|-----------------|----------|------------------------------|
| Erosion Control | Michael Harkins | Failed | Thursday, September 16, 2021 |

Corrective Action Required:

| | | |
|---|---------------------------------------|--|
| 1 | DCM2 ESC DEFICIENT INSTALLATION | DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. MAINTAIN SILT FENCE CLEAN GRAVEL FROM STREET |
|---|---------------------------------------|--|

Corrective Action Required:

| | | |
|---|---------------------------------------|---|
| 2 | DCM2 ESC DEFICIENT INSTALLATION | DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - MAINTAIN GUTTER BUDDY AT CURB INLET & REMOVE SEDIMENT BUILD UP - |
|---|---------------------------------------|---|

Corrective Action Required:

| | | |
|---|---|---|
| 3 | DCM1 ESC REQUIRED NO FURTHER INSP | EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE. - MAINTAIN SILT FENCE - - REMOVE TRASH & SEDIMENT BUILD UP AT CURB INLET - |
|---|---|---|

Comments: