

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210567
Address: 3053 NW THOREAU LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mark Harding	Failed	Friday, September 17, 2021

Corrective Action Required:

1	Misc	-Provide CSPF wall at master bedroom per plan , no plans. -Pan off return air space from soffit outside middle bedroom -Solid block joist ends above I beam; tie together opposite joists across I beam, need to check at next inspection.
---	------	--

Comments: