

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20211033  
Address: 4421 SW TANZANITE CIR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Patrick Schonfeldt	Failed	Tuesday, September 21, 2021

Informational:

1	Misc	-GARAGE PORTAL EXTERIOR OK
---	------	----------------------------

Corrective Action Required:

2	Misc	-Address floor joist at garage bored for DWV less than 2" from top end of joist- repair per submitted engineer letter -Address over bored dbl 2x10 joist for DWV at 1st floor bath, repair per submitted engineer letter - Strap plates - Dbl top plate requires 24" offset between plate breaks- see 2nd floor bed#4 -(4) 2X stud packs at all girder truss bearing ends per plans -see bedroom #4
---	------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

**Comments:**