CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20212446 Address: 4805 NE FREEHOLD CT, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Friday, September 24, 2021
Corrective Action Requ	ired:		
1 Misc	 Provide 2 anchors fo Garage PFH wall sear Anchor garage sill pla Nail corner studs per Shim gap under gara Install exterior door Provide solid suppor inside return air space Fb dead space outsic Remove all excess in Complete sump pur Security blocking for Provide solid blockir Move gas line out of Seal penetrations of Support gas csst line Protect plumbing at door Fb front basement b exterior wall verticall 	 Provide 2 anchors for each garage PFH wall with 2"x2" washer -Garage PFH wall seams must be within 2 ft of mid-trimmer height -Anchor garage sill plate within 12" of breaks. Min 2 anchors per plate -Nail corner studs per code -Shim gap under garage studs -Install exterior door frames per security code -Provide solid support under master bedroom ceiling beam support studs inside return air space -Fb dead space outside master bedroom from roof -Remove all excess insulation material from the fireplace space -Complete sump pump piping to outside -Security blocking for basement exterior door -Provide solid blocking underneath great room I beam support studs -Move gas line out of the return air space -Seal penetrations of ceiling return air space -Support gas csst line every 32" and min 3" above bottom of joists -Protect plumbing at bottom wall plate in front basement bedroom, near 	

outside bedroom above hallway at toilet

-Basement waste stack clean out shall be accessible

-Support plumbing above basement bedroom and bathroom at 4' of less

-Pan off return air space from fur down ceiling space above rear basement bedroom closet

**OK TO INSULATE

Comments: