

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20191614  
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Robb Popp	Partial	Monday, September 27, 2021

Informational:  
1            THIRD FLOOR            —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*  
COMPLETE

\*\*\*BUILDING B\*\*\*  
COMPLETE

\*\*\*BUILDING A\*\*\*\*  
-COMPLETE

Informational:  
2            SECOND FLOOR            —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*  
COMPLETE

\*\*\*BUILDING B\*\*\*  
COMPLETE

\*\*\*BUILDING A\*\*\*  
CORRIDOR CEILINGS TO SHAFT WALL

Informational:		COMPLETE EXCEPT 2044
3	FIRST FLOOR	— AREAS APPROVED —
		***BUILDING C***
		CORRIDOR CEILINGS TO SHAFT WALL
		ROOMS:1015,1017,1020-1030
		STAIRWELL WALLS AND CEILING
		***BUILDING B***
		CORRIDOR CEILINGS TO SHAFT WALL
		ROOMS: 1002-1015
		STAIRWELL WALLS AND CEILING
		***BUILDING A***
		CORRIDOR CEILING TO SHAFT WALL
		EXTERIOR WALL 1032 OK TO INSULATE
		STAIRWELL WALLS AND CEILING
		ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059, 1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058
		ROOM 1041 OK FOR SOFFIT FRAMING
		STAIRWELL WALLS AND CEILING
		SOFFIT FRAMING 1049,1052, CORRIDOR1060,1036
		**MCAL BUILDING**
		--- PRE ROCK:
		MECHANICAL ROOM 165 NORTH WALL
		ROOM 156
		Kitchen 164 OK-CEILING OK FOR ROCK NOT AT HOODS
		CORRIDOR 167 TO 10' FROM SHAFT WALL
		CORRIDOR 169,172,176,177a,177 to rm 135, 173, 34,39,42
		MC EXTERIOR WALLS OK FOR FOAM
		MC SHARED SPACES OK FOR RC 149-160, 162,162A,163 to truss repair, 174, 174A,175,179A
		MC UNITS 1-18, 21,24,28-33, 36,37
		SHARED SPACES: 149,150,152,153,154,157,159,162, 174,174A, 175
		AL UNITS: 102-147
Corrective Action Required:		
4	Miscellaneous Correction	2044-INCOMPLETE
		2045-INCOMPLETE
		024-REPAIR TRUSS
		COMPLETE DRY SYSTEM IN ATTIC

Comments: