CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20211138

Address: 1201 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Storm Sewer Construction Inspection		Steve Robbins	Partial	Monday, September 20, 2021
Informational:				
1	Misc	Installed structure 200, 201. The end structure on 201 was installed. Pipe is being laid toward strucure 202.		
Informational:				
2	Misc	they laid 100 feet of 54 inch RCP pipe. They also set junction box 202 and curb inlet 203. They need to move the water main before they can connect to curb inlet 204. RP 8-11-21		
Informational:				
3	Misc	They poured collars for storm structures 200, 201, 202 and 203, then back filled all storm lines. RP 8-12-21		
Informational:				
4	Misc	They laid 275 feet of 18 inch HDPE storm pipe and set curb inlets 302, 303 and junction box 304. Plans don't call for a 301 structure. RP 8-16-21		
Informational:				
5	Misc	They laid 120 feet of 18 in 8-17-21	ch HDPE storm pipe. They a	llso set field inlet 305. RP
Informational:				
6 Informat	Misc ional:	They laid 85 feet of HDPE storm pipe and set field inlet 306. RP 8-19-21		
7	Misc	They laid 60 feet of 15 inc	h HDPE storm pipe and 80 fe	eet of 30 inch HP storm

pipe. Plans call for 30 inch RCP, but the crew informed me that it was changed.

Sent an email to Steve and Sue asking about the changes. RP 8-20-21

Informational:

8 Misc They laid 30 feet of 30 inch HP storm pipe and 130 feet of HDPE storm pipe.

They also set curb inlet 100A and field inlet 100B. Waiting on a letter from the engineer to approve the material change from RCP to HP storm pipe. RP

8-23-21

Informational:

9 Misc They laid 162 feet of 24 inch HDPE storm pipe, 35 feet of 24 inch HP storm pipe

and 105 feet of 15 inch HDPE storm pipe. They also set curb inlets 101 and

102, plus junction box 103. RP 8-24-21

Informational:

10 Misc They laid 245 feet of 15 inch HDPE storm pipe and 42 feet of 15 inch HP storm

pipe. They also set curb inlets 102.1, 104 and 105. They poured inverts for

junction boxes 203 and 103 along with collars. RP 8-25-21

Informational:

11 Misc They poured the rest of the inverts and collars today. Plans were approved to

lower the water line for the last storm structure remaining to be installed. RP

8-26-21

Corrective Action Required:

12 Misc Surveyors from Anderson Engineering miss marked survey stakes for curb inlets

and junction boxes. They are reshooting everything and will submit recommendations on how to fix the problem of structure locations. RP

8-27-21

Informational:

13 Misc They laid 55 feet of 54 inch HP storm pipe and set dentition basin outlet

control structure 205. RP 9-13-21

Informational:

14 Misc They poured collars and inverts today. RP 9-14-21

Informational:

15 Misc They laid 60 feet of 36 inch HP storm pipe and set junction box 402. RP

9-16-21

Informational:

16 Misc Redford is pourig the toe-walls for the storm pipe going into the detention

basin.

Comments: