

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210567
Address: 3053 NW THOREAU LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Failed	Wednesday, September 29, 2021

Corrective Action Required:

1	Misc	-Provide CSPF wall at master bedroom per plan **See plan. Header shall be no smaller than 2x12. Strap header from studs to top plate. see plan detail- -Strap from top plate to jack studs-See detail -Provide framing anchors at bottom where sheathing not overlapping rim joist-See detail
---	------	---

Comments: