

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211893
Address: 103 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Michael Harkins	Failed	Wednesday, October 06, 2021

Corrective Action Required:

1	DCM2 ESC DEFICIENT INSTALLATION	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - MAINTAIN SILT FENCE - - SOIL STOCKPILES SHOULD NOT BE LOCATED NEAR THE STREET, STORM INLETS, LOT ACCESS, OR ADJACENT PROPERTY LINES. ALL STOCKPILES MUST EITHER BE STABILIZED, COVERED, OR HAVE ESC AND BMPs INSTALLED AROUND BASE OF THE PILE -
---	---------------------------------------	--

Corrective Action Required:

2	DCM2 ESC DEFICIENT INSTALLATION	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - MAINTAIN GRAVEL FILTER AT DRIVEWAY - - CLEAN STREET & GUTTERS -
---	---------------------------------------	---

Comments: