CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210156

Address: 2042 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Driveway Inspection Adam Nacke Failed Thursday, October 07,

2021

Informational:

1 Misc Forms were placed and aggregate was present and compacted. There is 2

water valves in the driveway approach. I informed them that we have to

have access to them after they pour the approach. RP 8-2-21

Corrective Action Required:

2 Misc Both water valve risers are busted. Need to remove and replace with new

risers. RP 8-6-21

Corrective Action Required:

Misc 10-7-21 2:05 AN Water Department came out and inspected the water valves

and determined that both the risers need to be replaced because they can't

get their valve key on the valves.

— Need new taller riser that the valve cover sits on properly . No gaps

between the cover and pipe.

-Riser needs to be the approved pipe

-Riser needs to be straight up and down, not at an angle.

Comments: