

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20210948  
Address: 306 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:            | Inspector:    | Outcome: | Date:                       |
|------------------------|---------------|----------|-----------------------------|
| <b>Erosion Control</b> | Shawn Hoffman | Failed   | Wednesday, October 20, 2021 |

Corrective Action Required:

|   |                                       |  |
|---|---------------------------------------|--|
| 1 | DCM2 ESC<br>DEFICIENT<br>INSTALLATION | DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.<br>- PROVIDE GRAVEL FILTER AT LOT ACCESS - |
|---|---------------------------------------|--|

Corrective Action Required:

|   |                                       |  |
|---|---------------------------------------|--|
| 2 | DCM2 ESC<br>DEFICIENT<br>INSTALLATION | DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.<br>- MAINTAIN SILT FENCE -<br>- MAINTAIN GUTTER BUDDY REMOVE SEDIMENT BUILD UP - |
|---|---------------------------------------|--|

Corrective Action Required:

|   |                                       |   |
|---|---------------------------------------|---|
| 3 | DCM2 ESC<br>DEFICIENT<br>INSTALLATION | DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.<br>- MAINTAIN ERIOSION CONTROL UNTIL SOD COMPLETE - |
|---|---------------------------------------|---|

**Comments:**