CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204198

Address: 125 NW MACKENZIE DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Wednesday, October

Residential 27, 2021

Corrective Action Required:

1 Misc -Garage portal ok

-Rear patio roof ok to cover

Corrective Action Required:

2 Misc -Maintain erosion control silt fence at front of lot, address before

rescheduling reinspection

-Fireblock between top plates at dbl wall at kitchen fridge/mud room

-dbl floor joists all locations at kitchen per plans, also dbl joist has been cut

for DWV

-security blocking at front door

-protect NM within 6' of attic access 2nd floor

-All Truss hangers per plans

-Dbl top plates require 24" offset between plate breaks, also address top

plate connection at corner intersection- 2nd floor East bedroom west corner

-add joist hanger at sgl joist to header connection, right of furnace at

basement

Comments: