## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20210625 Address: 2110 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:
		Michael Harkins	Failed	Wednesday, November 03, 2021
Correctiv 1	e Action Required: Miscellaneous Correction	: PFH Garage portal fra PFH garage portal fram Anchor bolts shall be ir	·	of plate
Correctiv	e Action Required:			
2	Miscellaneous Correction	<ul> <li>Provide LUS24 hangers girder truss B1 garage per truss plans</li> <li>Provide 4 stud pack at girder truss bearing points throughput per roof plan</li> <li>Nail studs at intersecting wall corners per plan</li> <li>Provide 5/8!anchor bolt in middle 1/3 the width of plate PFH portal frame garage</li> <li>Tighten anchor bolts garage</li> <li>Provide anchor bolt end of plate east wall garage</li> <li>Solid block soffit top plate to roof deck &amp; seal gaps west garage wall</li> <li>Furr out HVAC ducts in garage to allow for insulation</li> <li>Provide LUS24 hanger truss D1 bed 2 per truss plans</li> <li>Provide H2.5s @ dbl girder truss corner dining/great room</li> <li>Strap top plate SW corner bed 2 no plate overlap</li> <li>Seal fire blocking dead space next to refrigerator &amp; above</li> </ul>		

Seal upward penetration bottom plate kitchen Provide CS-PF nailing pattern & straps SGD & dining room windows Fire block fireplace Solid block & nail shearing breaks both sides fireplace Strap top plate master bedroom near tub Strap top plate corner master closet no plate overlap Seal duct between furnace & foundation wall Provide anchor bolts SCH 40 columns basement

**Comments:**