

Inspection Summary

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Informational:

2	SECOND FLOOR	—AREAS APPROVED—
		BUILDING C COMPLETE
		BUILDING B COMPLETE
		BUILDING A COMPLETE EXCEPT ELEVATOR

Informational:

3 FIRST FLOOR

—AREAS APPROVED—

BUILDING C
COMPLETE

BUILDING B
COMPLETE

BUILDING A
COMPLETE

MCAL BUILDING

Kitchen 164 OK-CEILING OK FOR ROCK NOT AT HOODS

CORRIDOR 167 TO 10' FROM SHAFT WALL

CORRIDOR 169,172,176,177a,177, 173, 34,39,42,48

MC UNITS 1-18, 21,24-33, 36,37,44,45,46

SHARED SPACES: 149,150,152,153,154,156,157,159,161,162, 162A,174,174A,175

AL UNITS: 102-147

164 walls ok except at column

Corrective Action Required:

4 Miscellaneous
Correction

KITCHEN AREA, Complete plumbing and sprinkler above ceiling

Comments: