

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRCOM20191614  
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Monday, November 15, 2021

Informational:	
1	THIRD FLOOR
	-AREAS APPROVED-
	BUILDING C COMPLETE
	BUILDING B COMPLETE
	BUILDING A COMPLETE EXCEPT ELEVATOR

Informational:	
2	SECOND FLOOR
	-AREAS APPROVED-
	BUILDING C: COMPLETE
	BUILDING B: COMPLETE
	BUILDING A: COMPLETE EXCEPT AT ELEVATOR

Informational:

3 FIRST FLOOR

-AREAS APPROVED-

\*\*\*BUILDING C\*\*\*  
COMPLETE

\*\*\*BUILDING B\*\*\*  
COMPLETE

\*\*\*BUILDING A\*\*\*  
COMPLETE

\*\*\*\*MCAL BUILDING\*\*\*\*

RM 165 NORTH WALL LAYER OVER SHAFT WALL  
1057 WALLS FOR ELECTRICAL GEAR  
RC OK ABOVE COOLER  
SCREW PATTERN AT WALLS AND CEILINGS FOR COOLER  
RC IN CORRIDORS FIRST 16" FOR SOFFITS: CORRIDORS  
167,176,177,177A,178A,169,172,173,39,42,31,34,48  
PRE ROCK AT CORRIDOR SOFFITS: 176,177,177A  
RC ROOMS 101-147, 181,182  
RC CHANNEL ROOMS: 102-153,161-163  
RC CORRIDORS 169,172,173,176,177a,177,48,39,42  
-SCREW PATTERN UNITS 1-18, 1041-1044  
-SCREW PATTERN CORRIDORS 160,169,172,173,176,177,177a walls  
-RATED LAYER AT BATHROOM CEILINGS 101-145, 147  
-SCREW PATTERN AT AT AL UNITS: 101-158, 161-163  
-RC AT MC UNITS 1-18,21,24-33, 36,45,46  
-RC SHARED SPACES 150-158, 162, 163,159,161,162A,170,171,179  
-RATED LAYER AT BATHROOMS 1-18,28,29  
-162 FIRST LAYER AT COLUMNS AND BEAMS, PRE ROCK FOR SOFFITS  
-SECOND LAYER AT COLUMNS 163 NORTH AND SOUTH WALLS OK  
-RATED LAYER AT 149,154,171, 162 TO UNFINISHED COLUMN  
-MCAL 2hr wall OK  
-SOFFITS IN CORRIDORS 177A, 177,176, 34,39,42,48  
-SCREW PATTERN MC THROUGHOUT  
-SEPARATION WALL AT IL/AL: IL SIDE 1st LAYET OK, AL SIDE 1st LAYER AT  
CORRIDOR OK, 2nd LAYER AT ROOM 166 OK

Corrective Action Required:

4 Miscellaneous  
Correction

-PROVIDE 5/8" GLASS MAT SHEATHING AT CANOPIES PER PLAN

Comments: