CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211979

Address: 516 SE DAVID RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Friday, November 19,

Residential 2021

Corrective Action Required:

1 Miscellaneous -Address LVL hip landing on multiple blocks at master bed

Correction -Seal through floor penetrations at kitchen island

-Have engineer clarify size and number of studs required at all beams as not

noted on plans

-Address holes bored closer than 2" and closer than 2" to bottom of triple

joists in bed 3(provide engineered letter for fix) -Seal joist penetration at return air in bed 5

-address return air panning in hallway between bed 4/5

Comments: