CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20212196

Address: 1630 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Pavement-Surface Adam Nacke Failed Monday, December

13, 2021

Informational:

1 Misc 11-6-21 AN 7:00am crew was out at Park ridge 7th and 8th mobilizing the

equipment to start paving the base layer with recycled type 5.

7:45am trucks are arriving with asphalt, road temp is 40deg and air temp is

39deg and rising.

8:25am asphalt has been running about 240deg in trucks and coming out of the paver around 280deg. I told one of the crew members and he called the

plant to turn up the temp on the mix

A new round of trucks just came in and the temp is a lot better around

270deg.

12:45pm one of seal o matic trucks hit a man hole and shifted it about 1ft. They moved it back in place and are going to box it off and keep paving so

Holthouse can come out and reset it. Pics attached.

1:17pm truck temps are still good, holding around 270 to 300deg

2:58pm they are about 3/4 the way done and everything looks good

11-7-21 all the base is done except around the damaged MH

Informational:

2 Misc 12-1-21 AN Seal o matic is cleaning the base asphalt in preparation for surface

later this week.

Informational:

3 Misc 12-2-21 AN 9:30am seal o matic is beginning to lay down the surface asphalt.

It is 56deg outside and asphalt temp is 290deg.

Corrective Action Required:

4 Miscellaneous 12-13

Correction

12-13-21 AN all surface is down. There only seems to be one problem at the intersection of hideaway dr and ne park springs terr. The street does not meet ADA spec between the two ramps on hideaway dr. I have voiced my concern that I didn't think they would be able to get under 5% to the

contractor and design engineer but no changes were made.

Comments: