# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20210347

Address: 1221 NE GOSHEN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Mark Harding Failed Friday, November 19,

Residential 2021

### Corrective Action Required:

1 Misc \*\*Install erosion control along the street

- -As-graded plot plan is required prior to sodding
- -Bottom of rear siding shall have min 2" of clearance from concrete slab; min 6" clearance to soil grade
- -Rear patio concrete floor poured right to siding. Address compliance with protection of wood siding and water entering into the basement.
- -Final grade, sod, downspout and sump pump extensions
- -Make sure that the sewer tracer wire and port are installed and available at grade level
- -Provide gfci protection for dish washer and laundry outlets per NEC 210.8(A) and (D). Receptacles not tripping when tested
- -Guardrail not compliant. Guardrail shall have maximum 4" openings between spindles when under min 50 lbs per square ft of load. Complete guardrail per code

# Corrective Action Required:

2 Misc NFM moved items into garage without approval.

Builder is to install plywood or sheetrock on all the guardrail that are not  $% \left( 1\right) =\left( 1\right) \left( 1\right) +\left( 1\right) \left( 1\right) \left( 1\right) +\left( 1\right) \left( 1\right) \left($ 

compliant.

2 items remain in house.

apply for a CMR for the issues on the exterior patio and provide all

documentation and code section.

Owner not to occupy without TCO and the 2 interior items addressed.

## **Comments:**