## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20211044

Address: 218 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

All Rough Inspection - Mitchell Schwarz Failed Friday, January 14,

Residential 2022

Corrective Action Required:

1 Miscellaneous : PFH GARAGE PORTAL FRAMING ONLY :

Correction PROVIDE SOLID BLOCKING AT SHEATHING BREAKS ABOVE DOOR AND NAIL

PER CODE

-nail intersecting wall corners 12" oc

-rafters not tied to ceiling joists and top plate per code, rafter landing on

multiple blocks throughout (2018 IRC R802.5.2)

-Frame and install jacuzzi tub master bath, rough opening access for

circulation pump and receptacle, land NM to box for tub

-fireblock at fireplace fireblock between studs at cabinet on hall side

-Nail all exterior sheathing per plans

-Unable to inspect covered patio framing with lid

## **Comments:**