

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211044
Address: 218 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mark Harding	Failed	Wednesday, January 19, 2022

Corrective Action Required:

1	Miscellaneous Correction	-rafters not tied to ceiling joists and top plate per code, rafter landing on multiple blocks throughout (2018 IRC R802.5.2) -Nail all exterior sheathing per plans -Unable to inspect covered patio framing with lid, provide ladder or remove soffit for inspection of roof framing.
---	--------------------------	---

Comments: