CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20213384Address:301 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Friday, January 21, 2022

Corrective Action Required:

1 Miscellaneous Correction	 Seal penetration of service entry cable Fur out around B-vent main floor closet and fire blocking Fur out hav/ac garage at double garage,Plate under header required 16d sinkers 3" on center 2 rows per plan 4x 2x6" under 16" LVLS by dining area , per plan Provide proper slope on waste drain vents in attic area Provide collar ties master bedroom Center post at deck not to detail in plans gas line not bonded clarify support and framing of fire place on deck , support rim or engineering
-------------------------------	--

Comments: