

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213385
Address: 121 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Not Ready	Tuesday, February 08, 2022

Corrective Action Required:

1	Miscellaneous Correction	Have engineer address rafters not connected to ceiling joists at top plates -Provide connection of post to beam at deck and covered deck -Nail rafters to lookouts at great room windows -Have engineer address hip and rafters not connected to top plate at master -Complete fireblocking in ceiling line at closet at bed 3 and at window bed 3 -Sheet rock and fireblocking required under dead space in stairs -(3) studs required at basement corner southeast
---	--------------------------	--

Comments: