

February 8, 2022

Summit Homes 120 SE 30th St. Lee's Summit, MO 64082

RE: Field Issue of over notched corner studs for Lot #37 Osage – 2118 SE Rutherford Dr. Lee's Summit, MO 64082 – Permit # PRRES20213404

This letter addresses the over-notched holes for electrical for Lot#37 Osage.

- Notches are approximately 1.5" x 1" maximum.
- Notches are located approximately mid-height on multiple corner studs at ends of 16' garage door opening.
- Studs have approximately 2.5' tributary width of roof loads of approximately 115 plf.
- Install (2) rotated studs or (1) typical stud as close as possible to notched studs on each side of notched studs.



Sincerely,

Bradley Huxol, PE