CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210729 Address: 2159 NW KILLARNEY LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector: Mark Harding	Outcome:	Date:	
			Failed	Tuesday, February 08, 2022	
Corrective	e Action Required:				
1	Miscellaneous Correction	 over drilled joist #3 strap and fire stop la strap top plate at ea corners. strap top plates mstrap strap top plate at re fill in and support jo 	nsualte do not cover inspection items. drilled joist #3 joist west of panel for home run of electrical- and fire stop laundry wall at top plate of 2nd floor. top plate at each end over landing where top plates do not intersect at s. top plates mstr bath wall where top plate elevationo is different. top plate at rear great room tall wall. and support joist at heat chase between basement and garagae. e 2 1/2" through bolts at all deck post to beam connections		

Comments: