

FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

BUSINESS NAME	THE PRINCETON		
ADDRESS	1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	O'REILLY BUILD LLC:	TELEPHONE	(417) 862-9500
ADDRESS 5051 S NATIONAL AVE STE 4-110 SPRINGFIELD, MO 65810 Primary: (417) 862-9500 Cell: <no cell="" phone=""></no>			

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

Occupancy 🔲 Ser	mi-Annual	Annual	Life Safety	Sprinkler	 Hazardous Material Permit
🔲 Complaint 🔲 Exp	olosive Storage	UST	Post-Incident	Open Burning	Other
CLASS:	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #
R-4	196K				

LOSS REDUCTION NARRATIVE

□ NO VIOLATIONS NOTED			□ ALL VIOLATIONS RESOLVED			
Last Inspection	1st Inspection	2nd Inspection	3rd Inspection		4th Inspection	
INSPECTION	INSPECTOR	OL	JTCOME	DATE		
Alarm Test	Craig Hill	Pa	artial	Tuesday,	February 08, 2022	
Sprinkler - Hydrosta	tic Test Craig Hill	Pa	assed	Tuesday,	January 04, 2022	

Sprinkler - Flow Test	Craig Hill	Partial	Tuesday, February 08, 2022			
Sprinkler - Hydrostatic Test	Craig Hill	Partial	Thursday, October 14, 2021			
Alarm Test	Craig Hill	Partial	Wednesday, February 09, 2022			
Sprinkler - Flow Test Craig Hill Failed Wednesday, February 09, 2022 Corrective Action Required: 1 Label sprinkler room door. Vednesday, February 09, 2022 1 Label sprinkler room door. Dry system in memory care failed, need to re-test. Vednesday, February 09, 2022 Add wrench to spare head box. Failed Wednesday, February 09, 2022						
Alternate Protection Systems Craig Hill Not Ready Wednesday, February 09, 2022 Inspection						
	INSPECTOR Craig Hill	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNA TURE			

I