



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	THE PRINCETON		
ADDRESS	1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	O'REILLY BUILD LLC:	TELEPHONE	(417) 862-9500
ADDRESS	5051 S NATIONAL AVE STE 4-110 SPRINGFIELD, MO 65810 Primary: (417) 862-9500 Cell: <NO CELL PHONE>		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: R-4	Map#: 196K	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Craig Hill	Partial	Tuesday, February 08, 2022
Sprinkler - Hydrostatic Test	Craig Hill	Passed	Tuesday, January 04, 2022

Sprinkler - Flow Test	Craig Hill	Partial	Tuesday, February 08, 2022
Sprinkler - Hydrostatic Test	Craig Hill	Partial	Thursday, October 14, 2021
Alarm Test	Craig Hill	Partial	Wednesday, February 09, 2022
Sprinkler - Flow Test	Craig Hill	Failed	Wednesday, February 09, 2022
Corrective Action Required: 1 Label sprinkler room door. Label riser with area of protection. Dry system in memory care failed, need to re-test. Add wrench to spare head box.			
Alternate Protection Systems Inspection	Craig Hill	Not Ready	Wednesday, February 09, 2022

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
February 09, 2022	Craig Hill	<input type="checkbox"/> Yes <input type="checkbox"/> No	