

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212347
Address: 146 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Robb Popp	Failed	Tuesday, February 15, 2022

Corrective Action Required:

1	DCM2 ESC DEFICIENT INSTALLATION	**9-7-22 DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - MAINTAIN SILT FENCE - - MAINTAIN GRAVEL FILTER - - STREET CLEANUP REQUIRED -
---	---------------------------------------	---

Corrective Action Required:

2	DCM5 ESC INSP DENIED	**2-15-22 REQUESTED INSPECTION DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. -PROVIDE EROSION CONTROL METHODS AT PERIMETER OF LOT, GRAVEL FILTER WITH MIN 6" OF LIFT OF 3/4" GRAVEL, PROTECT SWALE IN BACK, CLEAN SILT FROM STREET. EROSION CONTROL TO BE COMPLIANT WITHIN 2 BUSINESS DAYS
---	-------------------------	--

Comments: