

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20212347  
Address: 146 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Control</b>	Robb Popp	Failed	Tuesday, February 15, 2022

Corrective Action Required:

1	DCM2 ESC DEFICIENT INSTALLATION	**9-7-22  DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - MAINTAIN SILT FENCE - - MAINTAIN GRAVEL FILTER - - STREET CLEANUP REQUIRED -
---	---------------------------------------	---

Corrective Action Required:

2	DCM5 ESC INSP DENIED	**2-15-22  REQUESTED INSPECTION DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. -PROVIDE EROSION CONTROL METHODS AT PERIMETER OF LOT, GRAVEL FILTER WITH MIN 6" OF LIFT OF 3/4" GRAVEL, PROTECT SWALE IN BACK, CLEAN SILT FROM STREET. EROSION CONTROL TO BE COMPLIANT WITHIN 2 BUSINESS DAYS
---	-------------------------	--

Comments: