

Inspection Summary

Permit #:PRRES20210734, Building Permit - Residential
Address: 1514 SW HEARTWOOD DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Sewer Service Inspection - R	Steve Robbins	Failed	

Corrective Action Required

1	Miscellaneous Correction	It appears that the MH (4511) in the back of the lot has been hit, there is also debris in the line. Contractor needs to make corrections to the MH.
---	--------------------------	--

Comments: