

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212568
Address: 3061 NW THOREAU LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Wednesday, March 09, 2022

Corrective Action Required:

2	Miscellaneous Correction	<ul style="list-style-type: none">- No fire blocking anywhere no further inspections until this is complete- No sliding door main floor- Boca plate DWV floor bathroom at garage- Nail all exterior intersecting corners to code- Address 2x6" studs cut and not full length either side of windows in hearth room- Provide joist hanger on double at bottom of stairs basement- Provide joist hanger at cantilever joist at exterior wall straight across from stairs basement- Nail hanger at double joist 6' out from bottom of stairs- Missing stud basement stairs riser- Address loose snow blocking in master suite- Gap in top plate master shower- Provide triple truss hanger for girder to girder connection at master bathroom A1-W6- Provide window front middle bedroom- Complete vent ductwork bathroom second floor middle- Strap top plate second floor middle bedroom left of window- Truss E7 not nailed to bracket second floor sitting room
---	--------------------------	---

Comments: