CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Robb Popp Failed Friday, March 18, 2022

Commercial

Corrective Action Required:

1 Miscellaneous

Correction

- -COMPLETE CORRECTIONS FOR ALL OTHER DEPARTMENTS
 -INSTALL LOUVERED COVERS FOR FRESH AIR AT ROOFTOPS
- COLUMN TO THE COURT OF THE COLUMN TO THE COL
- -COMPLETE ALL EXTERIOR ELECTRICAL, MECHANICAL, ETC IN COURTYARD,

CARPORTS AND ALL OTHER LOCATIONS

- -REPAIR DAMAGED SITE LIGHTING AT NORTH AND NORTHWEST -COMPLETE SITE ELECTRICAL AT FLAG POLE. MONUMENT SIGN
- -WEST COURTYARD- GFCI NOT WORKING
- -EAST COURTYARD- SECURE WHIP IN STORAGE CLOSET, LAND ELECTRICAL AT

FOUNTAIN

UNITS

- -AL EAST EXTERIOR TERMINATE WATER LINE
- -COMPLETE SIDEWALKS FOR EGRESS
- -SECURE GFCI SOUTHWEST CORNER
- -PROVIDE TAMPER RESISTANT SCHRADER VALVE COVERS AT COURTYARD
- -REMOVE JOB TRAILERS AND COMPLETE SIDEWALK
- -PROVIDE AFCI PROTECTION THROUGHOUT PER ARTICLE 210.12
- -SUBMIT 3RD PARTY INSPECTION FOR FOOTINGS AT CARPORTS

175-HAMMER ARRESTORS AT DISHWASHER 107- ADJUST DOOR TO CLOSE AND LATCH

178-PROVIDE WORKING SPACE AT PANELS PER ARTICLE 110

Corrective Action Required:

2 THE FOLLOWING

All residential units and common spaces in buildings A,B and C, and kitchen

AREAS ARE 164 approved for Occupancy

APPROVED

Comments: