

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20210354

Address: 2101 SW M 150 HWY, LEES SUMMIT, MO 640823902 SW PRYOR RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Sediment Control (ESC) Inspection	Tom Taylor	Failed	Friday, March 18, 2022

Informational:

1 Misc

Erosion Control failed. The snow melt from recent snowstorms have created muddy roads and failing erosion measures.

On 3.18.2022 Friday Erosion measures have failed. All roads are very muddy. Erosion Fencing on SW Rutherford Drive has fallen over and mud is in the roads. There is no erosion control measures on SW Osage Drive.

On 3.23.2022 All roads are muddy

Comments: