CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063

(816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213323

Address: 3813 SW WALSH DR, LEES SUMMIT, MO 640823811 SW WALSH DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Patrick Schonfeldt Failed Wednesday, March 23,

2022

Corrective Action Required:

1 Misc UNIT 3811:

- -fire rated plywood required within 4' of firewall
- -steel C runner cap required at top of fire rated rock against roof deck, see detail page A7.0 plans
- -secure all breakaway clips at fire rock
- -repair any damaged sections of fire rock
- -rated fire separation wall required between units per plans design A7.0 at basement SE corner
- -Fire caulk fire wall penetrations by SE cable at basement, Refer to A7.1 for detail

UNIT 3813:

- -fire rated plywood required within 4' of firewall
- -steel C runner cap required at top of fire rated rock against roof deck, see detail page A7.0 plans
- -secure all breakaway clips at fire rock
- -repair any damaged sections of fire rock
- -breakaway clips required per design spacing, see A7.0, see 2nd floor
- -H stud required at fire rock breaks, see A7.0, see 2nd floor
- -rated fire separation wall required between units per plans design A7.0 at basement NE corner

-Fire caulk fire wall penetrations by SE ca	able at basement, Refer t	o A7.1 for
detail		

Comments: