

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20212568  
Address: 3061 NW THOREAU LN, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Shawn Hoffman	Failed	Wednesday, March 30, 2022

Corrective Action Required:

1	Miscellaneous Correction	<ul style="list-style-type: none"><li>- No sliding door main floor</li><li>- Nail all exterior intersecting corners to code 2 nails at 12" oc</li><li>-- Address 2x6" jack studs cut and not full length either side of windows in hearth room</li><li>- -Gap in top plate master shower</li><li>- -Provide window front middle bedroom</li></ul>
---	--------------------------	---

3/30/22

New items

- fire block plenum space at study/ living room chase
- Fire block HVAC chase at atrium
- Fire block end of chase east bathroom top
- Nail exterior siding 2 floor south east closet
- Fire block gaps in blocking 2 floor stairs landing above south bedroom doorway
- Fire block from joist space chase living room at fire place
- Tape seams in return air pan out at bathroom/ and HVAC garage wall
- Fire block floor penetration for steel columns first floor

**Comments:**