

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #:PRPWRW20216537, Public Works Right of Way Permit  
Address: 15 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Bob Burns	Partial	Thursday, March 31, 2022

**Corrective Action Required**

1	Misc	Crews are working along Town Center BLVD. Trucks are parked off of pavement in the grassy areas. There is some rutting that will need restoration.
---	------	--

**Corrective Action Required**

2	Misc	No workers onsite (cold). All open pits along Town Center and Colbern are securely fenced.
---	------	--

**Corrective Action Required**

3	Misc	I met with the contractor and gave him permission to core the sidewalk in front of the Honda dealer on Colbern Road. This is a 10' walk and will not require a full panel replacement.
---	------	--

**Corrective Action Required**

4	Misc	Crews are onsite and working along Douglas. All pits are properly fenced.
---	------	---

**Corrective Action Required**

5	Misc	Crews are working in MODOT ROW boring under 470. Crews have also performed several core holes to locate utilities in the intersection of Douglas and St. Luke's BLVD.
---	------	---

**Corrective Action Required**

6	Misc	Site visited drove the whole project and it appears they are complete and have done restoration. Will come back in a month to check again.
---	------	--

**Corrective Action Required**

7	Miscellaneous Correction	All grass areas have had topsoil, seed, and straw placed. The section of multi-use path that was poured back by the Honda dealer appears to be sub-standard and not KCMMB4K concrete. I sent a text to Chris and will wait for a response.
---	--------------------------	--

**Comments:**

