## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20210101Address:329 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Erosion Control Michael Harkins Failed Monday, March 28, 2022   Corrective Action Required: DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - MAINTAIN SILT FENCE - - MAINTAIN SILT FENCE - - MAINTAIN GRAVEL FILTER - - PROVIDE ADDRESS -   Corrective Action Required: 2 DCM5 ESC INSP REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION.   2 DCM5 ESC INSP MAINTAIN SILT FENCE -   2 DCM5 ESC INSP REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION.
1DCM2 ESCDEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - MAINTAIN SILT FENCE - - MAINTAIN GRAVEL FILTER - - PROVIDE ADDRESS -Corrective Action Required: 2DCM5 ESC INSP DENIEDREQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. MAINTAIN SILT FENCEMAINTAIN SILT FENCEMAINTAIN SILT FENCE
DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED. INSTALLATION - MAINTAIN SILT FENCE - - MAINTAIN GRAVEL FILTER - - PROVIDE ADDRESS - Corrective Action Required: 2 DCM5 ESC INSP DENIED REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. MAINTAIN SILT FENCE
INSTALLATION - MAINTAIN SILT FENCE - - MAINTAIN GRAVEL FILTER - - PROVIDE ADDRESS - Corrective Action Required: 2 DCM5 ESC INSP DENIED REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. MAINTAIN SILT FENCE
Corrective Action Required: 2 DCM5 ESC INSP DENIED REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. MAINTAIN SILT FENCE
- PROVIDE ADDRESS - Corrective Action Required: 2 DCM5 ESC INSP DENIED REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. MAINTAIN SILT FENCE
Corrective Action Required: 2 DCM5 ESC INSP REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL DENIED INSTALLATION. MAINTAIN SILT FENCE
2 DCM5 ESC INSP DENIED REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL INSTALLATION. MAINTAIN SILT FENCE
DENIED INSTALLATION. MAINTAIN SILT FENCE
MAINTAIN SILT FENCE
MAINTAIN GRAVEL FILTER
Corrective Action Required:
3 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS
DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.
INSTALLATION
- MAINTAIN SILT FENCE UNTIL SOD COMPLETE -
Corrective Action Required:
4 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS
DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.
INSTALLATION MAINTAIN SILT FENCE UNTIL SOD COMPLETE

**Comments:**