CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063

(816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215180

Address: 2020 SW WHEATFIELD CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Wednesday, April 20,

Residential 2022

Corrective Action Required:

1 Misc PROVIDE COMPLETE SET OF PLANS FOR REINSPECTION

Mitchell Schwarz 04/20/2022 9:34 AM

- -uncover front patio to inspect framing
- -collar ties 4' OC (garage)
- -PFH strapping per plans
- -nail all intersecting wall corners 12" OC
- -seal top plate penetration left of garage entry
- -complete bath fan exhaust (entry bath)
- -seal bottom plate penetrations garage entry bath
- -stud packs per plans under lvl entry bath N wall
- -provide plumbing in prep kitchen for sink
- -fire block furr down in prep kitchen
- -fire block pantry wall to ceiling space behind furr down. Seal gaps
- -complete furr down for dwv and plumbing above kitchen
- -IvI header above sliding read door per plans
- -un cover covered patio for inspection
- -address header/beam connection right of slider s3.2 10
- -address rear great room windows not framed to plans
- -seal floor penetration for cables at fireplace

- -seal gap for fireplace wall into furr down
- -missing joist hanger above master suite hall entrance also hanger missing nails
- -seal open end into furr down in master suite SW corner
- -seal bottom plate penetration master bath NE corner
- -address front door framing not to plans
- -Stud pack at 2nd floor supporting lvl plans call for 8studs
- -Protect Nm within 6' of attic access 2nd floor
- -fire block basement stairwell wall to ceiling space
- -steel columns in basement to be of correct size
- -seal penetration in return air panning in basement
- -install all windows
- -provide pressure gauge at gas line for inspection
- -bond gas line before first csst connection
- -anchor bolts within 6" of sill plate break E basement wall
- -address piers poured without inspection

Comments: