

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20214943
Address: 1721 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---|--------------------|----------|-------------------------|
| All Rough Inspection - Residential | Patrick Schonfeldt | Failed | Tuesday, April 26, 2022 |

Corrective Action Required:

| | | |
|---|------|--|
| 1 | Misc | -Garage PFH wall anchor must be located within middle 1/3 of sill plate -Support ridge above deck -Strap rear dining CSPF wall header and nail siding to header and rim band per A/4 detail (CHECK EXTERIOR NAILING AT REINSPECTION) -Provide information on capacity of the hanger of the 12"-18" lvl connection **OK TO INSULATE** |
|---|------|--|

Comments: