## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20215297

Address: 1522 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Friday, April 29, 2022

Residential

Corrective Action Required:

1 Misc

- -Seal top plate penetration W garage wall
- -seal top plate penetration garage entry
- -front entry wall not tied to garage or bed 3 wall -address tuss at bed 3 not tied to structural wall
- -uncover (2)2x10 at front patio for inspection
- -address broken truss above bed 2
- -seal top plate penetration in pantry
- -fire block dead space at bed 1 entry and seal penetrations
- -fire block top plate penetration at bed 1 bath
- -seal hole at island not being used
- -add blocking under kitchen island as needed
- -support gas at water heater
- -inspect exterior at time of re-inspect PFH nailing good

**Comments:**