



LEE'S SUMMIT MISSOURI



FIRE DEPARTMENT

NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	PETSUITES OF AMERICA		
ADDRESS	250 NW MCNARY CT, LEES SUMMIT, MO 64086		
OWNER/OPERATOR NAME	BEAR CONSTRUCTION SERVICES:	TELEPHONE	(913) 674-8004
ADDRESS	9218 METCALF #311 OVERLAND PARK, KS 66212 Primary: (913) 674-8004 Cell: (913) 238-0081		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	
2. _____	
3. _____	
4. _____	

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: B	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☐ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Craig Hill	Not Ready	Tuesday, April 12, 2022
Sprinkler - Hydrostatic Test	Ben Hicks	Passed	Friday, March 18, 2022
Sprinkler - Flow Test	Craig Hill	Failed	Tuesday, April 12, 2022

Fire Line - Hydrostatic Test Joe Starlin Passed Friday, October 29, 2021

Alarm Test Craig Hill Failed Friday, April 15, 2022

Sprinkler - Flow Test Craig Hill Passed Friday, April 15, 2022

Alarm Test Craig Hill Passed Monday, April 18, 2022

Corrective Action Required:

1 Alarm strobes need to terminate on silence.

Occupancy Inspection - Fire Craig Hill Temporary C of O Monday, April 25, 2022

Corrective Action Required:

1 Mount Exit signs on exterior gates.
Exterior gate locks need to have panic hardware or shall be readily openable from the egress side without the use of a key or special knowledge or effort. Until this can be done the gates need to remain unlocked.

Occupancy Inspection - Fire Craig Hill Failed Wednesday, May 04, 2022

Corrective Action Required:

1 Exit sign needs to be added to the north vinyl gate. Move double exit sign to the North one exit.
Exterior gate locks need to have panic hardware or shall be readily openable from the egress side without the use of a key or special knowledge or effort. Until this can be done the gates need to remain unlocked.

DATE OF REPORT

May 04, 2022

INSPECTOR

Craig Hill

PREVENTION FOLLOW-UP
REQUIRED?

☐ Yes ☐ No

RESPONSIBLE SIGNATURE