

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20215570  
Address: 2361 SW HICKORY LN, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Shawn Hoffman	Failed	Friday, May 13, 2022

Corrective Action Required:

- |   |                          |   |
|---|--------------------------|---|
| 1 | Miscellaneous Correction | <ul style="list-style-type: none"><li>- Nail exterior corner single bay garage at top 1/3</li><li>- Address gap at bottom of king stud at bottom of I beam single bay garage</li><li>- Complete fur out laundry room</li><li>- Fire block penetrations in plenum space at laundry</li><li>- Fire block DWV in plenum space at laundry</li><li>- Fire block top and bottom plate opening for ductwork at master toilet</li><li>- Support ridge in loft</li><li>- Fire block chase top plate upper floor next to stairs</li><li>- Provide anchor bolt at plate break basement</li><li>- Solid block cantilever at basement</li><li>- Improper clamp at UFER</li></ul> |
|---|--------------------------|---|

**Comments:**