

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20213954

Address: 2015 SW OSAGE DR, LEES SUMMIT, MO 64082 2017 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Patrick Schonfeldt	Failed	Monday, May 16, 2022

Corrective Action Required:

1 Misc

UNIT 2015:

- fire rock required to be seated in H stud
- repair damaged sections of fire rock above 1st floor 1/2 bath
- smart siding cannot be used to repair fire rock
- provide UL cert and specs for gray caulking used on firewall
- seal through penetrations for firewall SE cable basement

UNIT 2017:

- fire rock required to be seated in H stud per plans
- repair damaged sections of fire rock
- provide UL cert and specs for gray caulking used on firewall

Comments: