CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216495 Address: 101 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Control		Michael Harkins	Failed	Thursday, May 19, 2022
Corrective Action Required:				
1	DCM1 ESC REQUIRED NO FURTHER INSP	EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.		
Corrective Action Required:				
2	DCM6 ESC INSP DENIED STREET CLEAN UP	REQUESTED INSPECTION(S) DENIED. STREET CLEAN UP REQUIRED IMMEDIATELY, AND SHALL BE COMPLETED PRIOR TO REQUESTED INSPECTION(S) BEING PERFORMED.		
Corrective Action Required:				
3	DCM2 ESC DEFICIENT INSTALLATION	DEFICIENT EROSION CONTE UNTIL ADEQUATE EROSION	ROL INSTALLATION. NO FUR I CONTROL PROVIDED.	THER INSPECTIONS
		MAINTAIN GRAVEL FILTER 3/4 INCH DIAMETER OR LA	WITH AGGREGATE SHALL BE RGER	MINIMUM OF 6" OF
Corrective Action Required:				
4	DCM1 ESC REQUIRED NO FURTHER INSP	•	RED. NO FURTHER INSPECTI ON CONTROL IS INSTALLED A	
		PROVIDE SILT FENCE MAINTAIN GRAVEL FILTER CLEAN STREET		

Comments: