

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20214080

Address: 2005 SW OSAGE DR, LEES SUMMIT, MO 64082 2003 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Not Ready	Friday, May 20, 2022

Corrective Action Required:

1 Misc

UNIT 2003

- Fire stop chase in garage.
- Roof 4' plywood at front ridge.
- No vents or openings first 4' rated plywood Address damaged fire rock

UNIT 2005

- Fire stop garage chase
- Drilled holes in bottom 2" of joist, repair per engineer letter
- no vents or openings within first 4' of rated wall plywood
- Missing "C" channel at top of shaft walls, have engineer address repairs to UL design submitted, sheet metal faced nailed to fire rock and fire caulk painted on to repair damaged fire rock
- Address damaged fire rock

Comments: