

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20215570
Address: 2361 SW HICKORY LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Monday, May 23, 2022

Corrective Action Required:

1	Miscellaneous Correction	<ul style="list-style-type: none">- Address gap at bottom of king stud at bottom of I beam single bay garage- Complete fur out laundry room (fireblock)- Fire block penetrations in plenum space at laundry (RA joist space above laundry)- Fire block DWV in plenum space at laundry (RA SPACE)- Provide anchor bolt at plate break basement
---	--------------------------	---

Comments: