

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20215871  
Address: 2034 SW RED BARN LN, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Mitchell Schwarz	Failed	Monday, May 23, 2022

Corrective Action Required:

1	Misc	-address rafters landing on blocks though out -fire block top of furr out wall in dining -address l bracket used for hanger above kitchen next to lvl -fireblock furr out under beam next to great room windows -address roof supports landing on non load bearing walls(office/bedroom) -missing joist hanger above basement stairs -seal/fireblock bed 4 E wall into furr down -seal/fireblock bed 4 to bath wall into furr down -fireblock dead space to furr down in great room basement -fireblock dead space at wet bar - 2x4's furr down in wet bar requires joist hangers -fire block furred out wall to furr down in bath near wet bar -seal penetrations In joist space used for RA near above area -provide minimum 10psi at gas gauge for inspection -upload I-joist plans for inspection -cs-pf per plans
---	------	---

Comments: