CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20216173

Address: 2039 SW HOOK FARM DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Not Ready Thursday, May 26, 2022

Residential

Corrective Action Required:

1 Misc

- -frame and nail PFG garage to plans/code (triple bottom plate, anchor bolts not in middle 1/3 of plate)
- -anchor bolts within 12" of plate breaks (single car S wall)
- -fire block hvac chase into furr down in garage
- -missing nails in hangers above garage entry area
- -address 2x10 notched for RA at stairwell wall
- -missing nuts on bolts attaching ledger to beam (kitchen)
- -address rafters above great room windows landing on nothing(cut down just hanging)
- -uncover covered patio for inspection
- -fire block fireplace into ceiling spaces (when using Unfaced insulation, it must be packed tightly and securely)
- -complete plumbing for master tub (fireblock)
- -address new hole made for bath vent through joist above master shower
- -fire block E bed 3 and bed 3 closet wall to ceiling space
- -fire block furr down ends in basement
- -fireblock vertical to horizontal every 10' in basement (seal penetrations, when using Unfaced insulation must be packed tightly)
- -fireblock furr out walls in basement to ceiling line(if using Unfaced insulation must be packed tightly and securely)

- -seal penetrations in RA panning in furr down bed 7bath
- -install all beams to plans
- -attach post to beam at deck per plans

Comments: