CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20214745Address:130 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Friday, May 27, 2022

Corrective Action Required:

1	Miscellaneous	- Block sheeting breaks garage	
	Correction	- Nail top plate to header per PFG detail	
		 Provide 1" clearance for B vent at garage top plate 	
		- Security blocking at door to deck 3 bays out	
		- I beam at kitchen wall calling for 7 studs	
		 Address rafters landing on blocks over I beam in great room 	
		- Fire block penetration floor in chase near stairs main floor	
		- Provide 3 studs both sides under double LVL over stairs, one side missing at	
		cripple wall and the other 2 pack not nailed together	
		 Solid block sheet breaks office and w-I rooms Complete ductwork master toilet 	
		- Finnish RA panning around plumbing in bedroom 3 basement multiple	
		locations	
		 Fire block top plate bedroom 2 shower exterior wall 	
		 Security blocking at basement door 3 bays out 	
		- Fire block fur out at top plate bedroom 4	
		 Fire block fur out at top plate bedroom 4 closet 	
		 Nail hangers on header at garage steps basement 	
		 Provide Egress window basement 	

Comments: