# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20215059

Address: 3041 NW THOREAU LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Shawn Hoffman Failed Wednesday, June 01,

Residential 2022

## Corrective Action Required:

1 Miscellaneous - plans call for 5 studs under both sides of I beam, garage

Correction - PFH portal frame 2x4 to LVL nail 2 rows on 3" o.c.

- PFH portal frame straps should include top plate

- Protect electrical 6' away from attic access

- Security blocking garage man door 3 stud bays out

- Provide LIB's through out

- Plans call for 3 studs under double LVL great room at elevator

- Security blocking 3 bays out deck door

- Snow block over bump out in dining room

- Nail corner bedroom 2 near entry at bottom

- Fire block soffit at I beam basement through out

- Missing joist hanger's under top stairs basement

- Land electrical in unfinished basement behind panel

- Provide joist hangers basement at elevator wall

### **Comments:**