

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220047
Address: 2102 SW RED BARN LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Wednesday, June 01, 2022

Corrective Action Required:

1 Misc

- address over notched studs at pfh for electrical
- anchor bolts to be in the middle 1/3 of sill plate
- fireblock top plate penetrations at furr out wall garage
- fireblock gap at top plate in furr out wall garage
- address attic access opening
- uncover covered patio for inspection
- fire block foyer wall to bed /hall and seal penetrations
- address hip rafter and ceiling joist at master NW corner
- fireblock above fire place
- install all windows and doors
- fire block above dining room cantilever
- midway strap all dwv 2" in diameter or less
- ? tighten anchor bolts in basement
- ? Anchor bolts middle 1/3 of plate at basement bedroom 4 and check entire wall
- ? Fire block gap at top plate basement bedroom 4 , closet 4, bedroom 3 closet
- ? Strap DWV 2" and under in basement

Comments: